


SERVICE



Wiring diagram

SV100/E





M	A1	F	R1	FN.1
Motor 0,18KW 2800 rpm 220 V	Large lighted 0-1 Switch	Fuse 15A	Right Resistance 1000W	Right Fan Motor 90 W 2400 rpm